


CLEARVIEW STOVES

Installation of Flexible Stainless Steel Liner

Detail of Chimney Top



**** IMPORTANT**

Weep holes must not be placed facing into the prevailing wind